

## ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION

MP 309.5 Dalton Highway

Division of Spill Prevention and Response Prevention and Emergency Response Program

## SITUATION REPORT

Dalton Highway Truck Rollover

MP 309.5 Diesel Release

SITREP#1

**SPILL #:** 14399904301

TIME/DATE OF DISTRIBUTION: 5:00 p.m. on February 12, 2014

POTENTIAL RESPONSIBLE PARTY (PRP): Eggor Enterprises, Inc. (Eggor)

**INCIDENT LOCATION**: Dalton Highway Milepost 309.5

**TIME/DATE OF SPILL:** An Eggor driver went off the road while hauling fuel to Deadhorse from North Pole at 11:24 p.m. on February 11, 2014. The spill was reported to ADEC by Eggor through the after-hours reporting line at 7:33 a.m. February 12, 2014.

**TYPE/AMOUNT OF PRODUCT SPILLED:** The spilled product is diesel fuel. Based on a gauging of the tank containing the fuel that has been recovered, Eggor estimates that the spill volume is 2188.5 gallons. **CAUSE OF SPILL:** Truck went off the road.

**SOURCE CONTROL:** Responders emptied the trailer and removed it from the accident site.

**RESPONSE ACTION**: Big State Logistics arrived on site shortly after the Eggor truck left the road. Big State Logistics was able to unload the remaining fuel from the trailer into an empty trailer. The fuel was then transported to Colville Inc. in Deadhorse. Colville Inc. is the owner of the fuel, and they provided to ADEC the volume measurement of recovered fuel from the trailer.

Eggor is working with Colville Inc. to mobilize response equipment and personnel. Initial assessment of the affected area is underway. No spilled fuel has been recovered at this time.

ADEC is mobilizing a responder to oversee the initial cleanup action.

**RESOURCES AFFECTED:** The area of impacted tundra and roadway is unknown at this time. Moose and caribou are commonly found in the region of the spill but no affects to wildlife have been reported.

**FUTURE PLANS AND RECOMMENDATIONS:** ADEC will continue to monitor the response actions and review plans being developed to clean up contaminated snow and soil.

**WEATHER:** Tonight: Overcast; low -30°F; north winds to 9 mph. Tomorrow: Mostly cloudy; high -28°F; north winds to 2 mph.


## **UNIFIED COMMAND AND PERSONNEL:**

Incident Commander: Mark Furness, Eggor Enterprises, Inc

SOSC: Tom DeRuyter, ADEC Field SOSC: Wes Ghormley, ADEC

TIME/DATE OF THE NEXT REPORT DISTRIBUTION: As conditions warrant

**FOR ADDITIONAL INFORMATION CONTACT**: Tom DeRuyter, SOSC, ADEC (907) 451-2145 http://www.dec.alaska.gov/spar/perp/response/sr\_active.htm



Map of Dalton Highway; the red circle shows incident location.

**AGENCY/STAKEHOLDER NOTIFICATION LIST:** This situation report was distributed to the agencies listed on the standard distribution list, which includes the governor's office, Senator Begich's office, State Emergency Operations Center, U.S. Department of the Interior, National Marine Fisheries Service, U.S. Fish and Wildlife Service, and other state agencies. This situation report was also distributed to the following agencies and stakeholders:

## NORTH SLOPE (Prudhoe Bay, Deadhorse, Point Hope, Point Lay, Wainwright, Barrow, Atqusuk, Nuiqsut, Kaktovik, Anaktuvuk Pass)

AGENCY / STAKEHOLDER	NAME	SENT VIA	ADDITIONAL INFORMATION	TELEPHONE	FAX
Eggor Enterprises, Inc	Mark Furness	Email	FurnessM@acsalaska.net	452-3602	
Colville Inc	Jeff Holder	Email	Jeffh@colvilleinc.com	659-3198	
ADF&G	Al Ott/Jack Winters	Email	al.ott@alaska.gov jack.winters@alaska.gov	459-7285 or 459-7279	
Attorney General Office	Steve Mulder	Email	Steve.mulder@alaska.gov	451-2811 or 269-5100	
North Slope Borough	Charlotte E. Brower	Fax	Mayor	852-0200	907-852- 0337
North Slope Borough	Rhoda Ahmaogak	Email	Planning Director rhoda.ahmaogak@north- slope.org	852-0440	
Senate T/ Nome	Donnie Olson	Email	Senator donny olsen@legis.stat e.ak.us	465-3707	
House 40/ Nuiqsut	Benjamin Nageak	Fax	Kotzebue 5/16-1/09 Juneau 1/10-5/15	465-4833 or (800) 782-4833	907-465- 4586
Native Village of Nuiqsut	Margaret Pardue	Email	Native.village@astacalaska.net	907-480-3010	